


**10**

|          | 10 | 11     | 12 | 13 | 14 | 15 | 16 |
|----------|----|--------|----|----|----|----|----|
| <b>I</b> | 20 | 20     | 30 | 30 | 30 | 30 | 30 |
| <b>L</b> | -  | *20/30 | 30 | 30 | 30 | 30 | 30 |
| <b>U</b> | -  | 30     | 30 | 30 | 30 | 30 | 40 |

\* DALLAS = 20




K1-1077795  
K1-1077796  
K1-1077797  
K1-1077798

**40**


|          | 10 | 11     | 12 | 13 | 14 | 15 | 16 |
|----------|----|--------|----|----|----|----|----|
| <b>I</b> | 40 | 40     | 60 | 60 | 60 | 60 | 60 |
| <b>L</b> | -  | *40/60 | 60 | 60 | 60 | 60 | 60 |
| <b>U</b> | -  | 60     | 60 | 60 | 60 | 60 | 80 |

\* DALLAS = 40




K3-06022  
Ø5 x 35 TX25




Example  
Beispiel  
Voorbeeld  
Example  
Eksempel




Max 100mm    Max 100mm    Max 100mm    Max 100mm    Max 100mm




Max 100mm    Max 100mm    Max 100mm    Max 100mm

**1**



10

**2**



Ø 4mm ∇ 25mm

40